RESOLUTION 2010-521

RESOLUTION OF THE TOWNSHIP OF BARNEGAT, COUNTY OF OCEAN, STATE OF NEW JERSEY, DENYING THE RELEASE OF MAINTENANCE BOND FOR HERITAGE POINT, SOUTH, SECTION 4, WATER SYSTEM FACILITIES

WHEREAS, Mignatti Companies, the developer of Heritage Point, South, Section 4 has requested a release of Maintenance Bond, Water System Facilities; and

WHEREAS, the Township Engineer has inspected subject site, and recommends denying the release of Maintenance Bond, Site Improvements due to the following deficiencies;

- 1. Water valve box on the southerly leg of the intersection of Vineyard Way and Minot Court needs to be cleaned out.
- 2. Hydrant across from #3 Minot Court must be turned to properly face the street.
- 3. Both water valve boxes at the intersection of Hatteras Way and Vineyard Way must be cleaned out.
- 4. All three water valve boxes at the intersection of Solomans Drive and Hatteras Way must be cleaned out.
- 5. Solomans Drive In front of house #6 the hydrant water valve box needs to be cleaned out.
- 6. Water valve box for the hydrant in front of house #42 Hatteras Way must be cleaned out.

THEREFORE BE IT RESOLVED by the Township Committee of the Township of Barnegat, County of Ocean, State of New Jersey that the request for release of Maintenance Bond for Heritage Point, South, Section 4, Water System Facilities is hereby denied based on the recommendation of the Township Engineer, in his letter dated November 12, 2010.

CERTIFICATION

I, Kathleen T. West, Municipal Clerk of the Township of Barnegat, County of Ocean, State of New Jersey do hereby certify that the foregoing resolution was duly adopted by the Barnegat Township Committee at their regular meeting held on the 20th day of December, 2010, at the Municipal Complex, 900 West Bay Avenue, Barnegat, New Jersey.

Kathleen T. West, RMC Municipal Clerk