RESOLUTION 2010-518

RESOLUTION OF THE TOWNSHIP OF BARNEGAT, COUNTY OF OCEAN, STATE OF NEW JERSEY, DENYING THE RELEASE OF MAINTENANCE BOND FOR HERITAGE POINT, SOUTH, SECTION 1, SANITARY SEWER SYSTEM

WHEREAS, Mignatti Companies, the developer of Heritage Point, South, Section 1 has requested a release of Maintenance Bond, Sanitary Sewer System; and

WHEREAS, the Township Engineer has inspected subject site, and recommends denying the release of Maintenance Bond, Sanitary Sewer System until the following items have been corrected:

- 1. Westport Sewer Pump Station: The grinder plates on the pumps have been damaged from construction debris. In addition, the pump impellers are pitted. Therefore, it remains for the grinder plates and the pump impellers to be replaced.
- 2. Westport Sewer Pump Station: Water leaks into the electrical cabinet when it rains. The water leak must be sealed and all water damage in the cabinet must be repaired.

THEREFORE BE IT RESOLVED by the Township Committee of the Township of Barnegat, County of Ocean, State of New Jersey that the request for release of Maintenance Bond for Heritage Point, South, Section 1, Site Improvements is hereby denied based on the recommendation of the Township Engineer, in his letter dated November 22, 2010.

CERTIFICATION

I, Kathleen T. West, Municipal Clerk of the Township of Barnegat, County of Ocean, State of New Jersey do hereby certify that the foregoing resolution was duly adopted by the Barnegat Township Committee at their regular meeting held on the 20th day of December, 2010, at the Municipal Complex, 900 West Bay Avenue, Barnegat, New Jersey.

Kathleen T. West, RMC Municipal Clerk